

These markers as
lagers in the area
when water displacement
occurred after rain.
Several lagers near
water 1' high occurred
very much smaller.

The area where loose wire dug is above next line - all loose excavations for above next line.

As there was a graduation
slope 1 to 5 meters
from top of park to
sloped - the lower
portion of tipoids below
and here is where the water
from the Tip would be
found.

50 boxes ding before red line.

